Rental charges WHM workshop (10ft):

Transport at customer cost.

Wellhead maintenance workshop includes:

Workbench and vice to offshore standard.

Light and power according offshore regulations.

Cabinets to store plenty of spares or other rope soap and dope.















- 10K Testpump with chart recorder, 10K test hoses and air hoses.
- Hytorq pump unit, Hytorq tool, hydraulic hoses, nut sizes pre-discussed.
- Grease pump complete with hoses, grease fitting and hoses.
- Pneumatic band saw for corroded wellhead bolts.
- Complete set of spanners, sockets, hammers and other hand tools.
- Test fittings, bleeder fittings, spare grease fittings.









